Vivek Kumar Tandon

ADVOCATE
Enrolment No.: D/436/1988
Former Addl. Standing Counsel (Civil), GNCTD
Former Senior Panel Counsel, Government of India

MINUTES OF MEETING OF INSPECTION (WEST DISTRICT) HELD ON 06.06.2023 BY THE COMMITTEE APPOINTED BY THE HON'BLE HIGH COURT

1. **Mundka**


Khasra No. 163 (4-16) Dada Dhobas Johar

It belongs to DDA. In most of the part of this area we find construction and very less part from the area earmarked for water body has been left out as open. Even the pond constructed is artificial and no water is seeping/going under the ground. It is also noticed that water is pumped out through tube well, which is the only source of water for the entire area.

Be that as it may no further construction shall be permitted and what is to be done for the existing construction will be seen later on. Endeavour should be made to have the catchment of water from outside road as well and plan to that affect be prepared an action be also under taken, as far as possible for collecting the water. Report be submitted on or before 24.07.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.

CamScanner





2. Mundka

Khasra No. 142 (3-1)

It belongs to DDA. Natural water body. It is reported at site that a Case is pending before Financial Commissioner regarding exchange of land. The papers of the said case kindly be provided for taking further action.

CamScanner





3. Mundka

Khasra No. 190/1 (09-00) Shishu wala Talab

It belongs to DDA. It is reported that TSS has also been completed by DDA, however there is some discrepancies in the TSS done by DDA and TSM done by Revenue Department, GNCTD. In order to avoid any discrepancies, meeting will be held between the two authorities and everything would be sorted out within 15 days from today.

CamScanner

It is also reported that there is some encroachment on the water body. The same has to be removed. A report be submitted by 24.06.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.





CamScanner



4. Hiran Kudna

Khasra No. 415 (16-10)

It belongs to DDA. The water body needs cleaning immediately. It is also noticed that garbage is being thrown into this water body. A board be installed indicating the area belongs to the water body and also that in case anybody is found throwing garbage or otherwise shall be challaned. The entire process be completed before the rainy season and proposed action as well as after completion be forwarded along with photographs (before and after) within one month. Report be submitted both in physical and digital form at email – vivekkumartandon@gmail.com,tandonadvocates@gmail.com

CamScanner





5. Hiran Kudna


Khasra No. 564 (16-05)


It belongs to DDA. Immediate steps to block the sewage is required to be undertaken. The water body needs cleaning immediately. It is also noticed that garbage is being thrown into this water body. A Notice board be installed indicating the area of the water body and also that in

CamScanner

case anybody is found throwing garbage or otherwise shall be challaned. The entire process be completed before the rainy season and proposed action as well as after completion be forwarded along with photographs (before and after) within one month.

Report be submitted both in physical and digital form at at email – vivekkumartandon@gmail.com,tandonadvocates@gmail.com





CamScanner

6. **Hiran Kudna**

Khasra No. 82/2 (03-06)

It belongs to DDA. Though as per sizra the area should be in square, however at site the entire area is divided through a Storm Water drain. Further, it is also noticed that storm water drain is filled up with sewage. How this happened is a big question mark and needs explanation. The three authorities i.e DDA, BDO and I&FC should submit a joint report within 3 weeks with support of the old records. Further action plan for the development be also prepared within the same time. Report be submitted both in physical and digital form at at email – vivekkumartandon@gmail.com,tandonadvocates@gmail.com



CamScanner



7. Hiran Kudna

Khasra No. 134 (11-16)

It belongs to DDA. It is reported that in the area of water body a Baraat Ghar, Mohalla Clinic and Road are also part of it. There appears to be some encroachment as well. TSS/TSM be thoroughly prepared and submitted to the committee. The existing water body needs cleaning. It is also noticed that garbage is being thrown into this water body. A Notice board be installed indicating the area of the water body and also that in case anybody is found throwing garbage or otherwise shall be challaned.

Report be submitted at email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.

CamScanner





8. Hiran Kudna

Khasra No. 184/1 (02-00)

It belongs to DDA.

CamScanner



9. Neelwal


Khasra No. 86 (08-11)

It belongs to DDA. Though it is reported that STP plant has been set up by Delhi Jal Board and is in working condition. However, none was present from the Delhi Jal Board to apprise actual facts. Further the cleaning of water body is extremely necessary which should be done on a war footing basis. Report be submitted by 26.06.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.

Exact demarcation be done so that it is encroachment free and if any encroachment is found the same may be removed immediately.

CamScanner


Latitude: 28.668367
Longitude: 76.979796
Elevation: 236.95±7 m
Accuracy: 11.4 m
Time: 06-06-2023 10:52
Note: 2-Neelwal-86
Powered by NoteCam


Time: 06-06-2023 10:51
Note: Neelwal-86
Powered by NoteCam

CamScanner



10. **Neelwal**

Khasra No. 55 (14-17)

It belongs to DDA. Cleaning is required. Action Plan be prepared and submitted by 24.06.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.

CamScanner





11. Tikari Kalan

Khasra No. 488 (02-14)

It belongs to DDA. Cleaning is required. Action Plan be prepared and submitted by 24.06.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.

CamScanner





12. Tikari Kalan

Khasra No. 487/3min (10-12)

It belongs to DDA. Natural water body needs cleaning and repairs. Action Plan be prepared and submitted by 24.06.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.

CamScanner





13. Tikari Kalan


Khasra No. 484min (6-14-1/2)1213 (0-3) Total Area (6-17-1/2)

After a long time a well maintained water body is found. However after going through the records it is found that outlet of water contains 20 BOD which is alarming. Efforts be made to reduce the said BOD as even after pilfiltration the same water be harmful when it meets underground water. The Delhi Jal Board have assured to bring


CamScanner

it to 10 BOD in a short span of time which too is on a higher side. Action Plan/Report be submitted within 2 weeks on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.






CamScanner



14. Tikari Kalan

Khasra No. 482min (19-7-1/2)

At site it was found that water is being dragged out through pumping machine and the water was being taken to Mungeshpur drain. The DDA to prepare a plan/scheme for development of water body within one month and report be submitted by 24.07.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.



CamScanner




15. Tikari Kalan

Khasra No. 478 (5-6)

It belongs to DDA. The condition of the water body is pathetic and needs immediate repairing and cleaning. Further, how it would be maintained should also be indicated.

Action Plan be prepared and submitted by 24.06.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.



CamScanner



16. **Nangloi Jat**

Khasra No. 126 (old 61/14/3) (8-12)

Artificial lake. All sewerage is flowing into it. It has floating rafter, blowers for aeration. The pond also has fish and small ducks.

Action Plan be prepared and submitted by 24.06.2023 on email – vivekkumartandon@gmail.com, tandonadvocates@gmail.com.



CamScanner



Note: Authorities are requested to submit compliance of the directions of Court Committee, within the stipulated time.

(Arvind Sah)
Court Commissioner
Commissioner

(Vivek Kumar Tandon)
Court

CamScanner